

United States of America
Department of Transportation — Federal Aviation Administration
Supplemental Type Certificate

Number SA4065SW

Project A4365SW-S
AAB-214

This certificate, issued to **Aero Logistics International
P. O. Box 34395
Dallas, Texas 75234**

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations.

Original Product — Type Certificate Number: 3A19

Make: Cessna

Model: 150, A, B, C, D, E, F, G, H, J, K, A150K, L, A150L, M, A150M, 152, A152

Description of Type Design Change: Installation of metal chip detector in engine oil according to Drawings 11-150-01 dated 12/29/78; 11-150-10 dated 12/29/78; 11-150-21 dated 1/20/79; 11-150-40, Revision A dated 10/5/79; 11-150-35 dated 10/27/78; and 11-150-50 dated 4/14/79, or later FAA approved revision.

Limitations and Conditions:

Aircraft must be placarded according to Drawing 11-150-50.

Compatibility of this modification with other previously approved modifications must be determined by the installer.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: **January 30, 1979**

Date reissued:

Date of issuance: **December 4, 1979**

Date amended:



By direction of the Administrator

Don P. Watson
(Signature)

Don P. Watson
Chief, Engineering and Manufacturing Branch
(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.